

Document No.: RN-240614-01
Date: June 14, 2024
Classification: External
Priority: Routine
Attn: All Customers
Related Products: FB250, Fleet One
Subject: **FB250, Fleet One Firmware Release Note – V2.0.1**

Dear Valued Customers,

Intellian is pleased to release upgraded firmware for the Intellian Fleet One and FB250. This firmware (FW) should be applied to the models shown in Table 1.

The priority of this FW update is considered 'Routine' as it includes regular update items. It is recommended to apply this update at your convenient opportunity.

***Note:** It is mandatory to upgrade to v2.0.1 from v2.0.0. Therefore, if the terminal isn't currently operating on FW v2.0.0 then, it is essential to install FW v2.0.0 before upgrading to FW v2.0.1

Table 1 Terminal Firmware Package Version

| No. | Product | Model Number | Previous Version | Release Version |
|-----|-----------|------------------------|------------------|-----------------|
| 1 | Fleet One | F4-A100-S | 2.0.0 | 2.0.1 |
| 2 | FB250 | F4-A250-S F4-A250-R | 2.0.0 | 2.0.1 |

The links for downloading the applicable Firmware Packages are included in Table 3.

Table 2 Summary

| Category | # | Contents | Applied | |
|--------------|-----|---|---------|-------|
| | | | FO | FB250 |
| New Function | 1.1 | MST related items are deleted in Aptus LX. | O | O |
| Improvement | 2.1 | Customer requirements updated (CTTIC) - Diagnostics test mode is now displayed in Operation mode - Change to prevent SIP Registration failure | O | O |

*For details on each item, please refer to 'Details' below


Table 3 Links to Download Firmware Packages

| Product | Firmware Package File | Version |
|-----------|----------------------------------|---------|
| Fleet One | Fleet One v2.0.1 | 2.0.1 |
| FB250 | FB250 v2.0.1 | 2.0.1 |

Details

1. New Function


- 1.1. MST related items are deleted in Aptus LX. Marine Safety Terminal (MST) functionality was implemented to support implementation of now discontinued GMDSS service.



2. Improvements

- 2.1. Update to requirements linked to a customer (CTTIC).

- Diagnostics test mode is now displayed in Operation mode. When diagnostics test mode is deactivated, SIP Registration failure will not be displayed once it is connected to the SIP Server within 5 minutes.
- Change to prevent SIP Registration failure when terminal first turned ON. Modified to forcefully send a “SIP Registration” message once every 5 minutes and if cannot be connected for over 5 minutes, the SIP Registration failure message will be displayed.



Contact Information

Please contact your local Technical Support team or Product Management team if you have any questions or require any additional information.

Thank you.

Product Management Team
Office: +82 31 379 1000
E-mail: PM@intelliantech.com

H.Q

Pangyo Office

Intellian Technologies, Inc.
3F IDIS Tower, 344, Pangyo-ro
Bundang-gu, Seongnam-si,
Gyeonggi-do, 13493 Korea

T +82 2 511 2244
F +82 2 511 2235

EMEA

Rotterdam Office

Intellian B.V.
Tempelhof 12
3045 PV Rotterdam,
The Netherlands

T +31 1 0820 8655
F +31 1 0820 8656

AMERICAS

Irvine Office

Intellian Technologies USA,
Inc.
11 Studebaker
Irvine, CA 92618 U.S.A.

T +1 949 727 4498
F +1 949 271 4183