

Cobham SATCOM

Lundtoftegaardsvej 93 D
2800 Kgs. Lyngby
Denmark

T: +45 39 55 88 00

F: +45 39 55 88 88

Date: December - 2019

Document Number: 95-170774-A

SAILOR 500/250/150 FleetBroadband
SAILOR Fleet One/EXPLORER 727/ 325

Software release version 1.26

Subject:

Please be informed that a new software version 1.26 for the following Cobham SATCOM products has been released:

- SAILOR 500 FleetBroadband TT-3740A
- SAILOR 250 FleetBroadband TT-3742A
- SAILOR 150 FleetBroadband TT-3744A
- SAILOR Fleet One TT-3744A-00581/00591
- EXPLORER 727 TT-3722A
- EXPLORER 325 TT-3721A

Priority:

- **MEDIUM:** It is recommended to apply this change / initiative to all units in stock. For units sold it is recommended to apply this change / initiative next time the system(s) is inspected.

Major changes from software version 1.25 to version 1.26:

- Admin login now working using HTTP cookie in web browsers
- MultiVoice adapted for support of a future Inmarsat network change
- The "Check for software updates" service in the web interface has been closed
- Security fixes

Bug-fixes


- General improvements

Action:

Download file **FBB_E325727_FleetOne_ver_126.zip** located at Cobham SATCOM Sync partner login: <https://sync.cobham.com/> - or at the Cobham SATCOM Sync Support section: <https://sync.cobham.com/satcom/support>. Save and extract to your hard drive.

Procedure for installing version 1.26


1. Make sure the terminal is switched on and connect the Ethernet cable to your PC
2. Open your web-browser and open the web interface of the terminal at address <http://192.168.0.1/>
3. Select **SETTINGS**.




4. Select **Upload**.



- Click **Browse...** locate and select the software file stored and extracted to **bganx_bdu_1_26-0001.dl**.
Click **Upload** and verify that the upload is in progress.



- When the upload is done, the terminal will reboot. Select the address <http://192.168.0.1/> again and verify that the software version is listed as **1.26, build 1**.



Please note that the terminal might start an antenna software upgrade after the reboot. Make sure that the upgrade has ended before disconnecting the antenna or switching the system off. **(All LEDs on the terminal must eventually turn green and no warning in the event list).**

- End of update procedure.