

Models Impacted by GPS Rollover Cycles - with Serial Number (S/N) DETAIL

	Dec. 20, 2020	SERIAL NUMBERS /Affected Core	June 20, 2021	SERIAL NUMBERS /Affected Core	Jan. 2, 2022 (JRC May 15th)	SERIAL NUMBERS /Affected Core	Update / Replace
Furuno	Felcom 15/16 w/ GPS GN79L5A	Before 3533-9371; Software Update 3.11 or 5.05			Felcom 15	GPS GN-8097 B/C/D; S/N 3533-9471 & After	Software Update may Fix or Felcom 18/19
Furuno	Felcom 16 w/ GPS GN79L5A	Before 3534-2756; Software Update 3.11 or 5.05			Felcom 16	GPS GN-8097 B/C/D; S/N 3534-2756 & After	Software Update may Fix or Felcom 18/19
Furuno	AIS FA100	GN79, ALL					FA170
Furuno	GPS GP310B w/ GN-79L2B-P	Replace GPS for S/N before 3453-5687 ; Cold Start MAY resolve S/N 3453-5687 & After					GP330B
Furuno			GPS GP32/37	GN-8091			GP39
Furuno			GPS GP320B	GN-8092C ; S/N 3473-6767 or before			GP330B
Furuno			GP80 and GP90/Dual GPS	GN-8091C/D, Replace Core with P/N 000-150-957			Update or GP170/170/D
Furuno			GP150/Dual GPS	GN-8091C/D Update software to latest release v4.025 to prevent			Update or GP170/170/D
Furuno			GPS GP1640, GP1650, GP1850	GN-8091C/D			Replace w GP1871F/ GP1971F GPS/ Plotter /Sounder
Furuno			GP3500/F - Chartplotter-GPS	GN-8091C/D and GN-8092C			Software Update pending..... (late 2020) to prevent
Furuno					AIS FA150	GN-8097H	Update transponder software to 4.07 to prevent or NEW FA170
Furuno					Felcom 18/19 (older Units)	GN-8097 B/C/D	Older units Req Software Update v1.20 or higher
Cobham Satcom	SAILOR 65xx GNSS/DGNSS						Software 1.11
Cobham Satcom	SAILOR 6004 Control Panel						Software 2.03 & APP
JRC					AIS JHS-182	BB51401 and after	JHS-183
JRC					Inm. C JUE-85	GR10251 to GR23738	ACS software version 1.00, 2.00 or 3.00
JRC					Mini-C JUE-95 SA	GR10051 to GR23188	ACS software version 1.00 or 3.00
JRC					Mini-C JUE-95 LT	GR13808 to GR23598	ACS software version 2.00 or 3.00
JRC					Mini-C JUE-95 VM	GR10251 to GR23738	ACS software version 1.00 or 3.00
JRC					FBB JUE-250	ALL	FleetBroadband JUE-251
JRC					GPS Navigator JLR-7700 MKII	Refer to JLR-4311	JLR-7600/7900
JRC					GPS Rec. JLR-4300	KE54239 and after	
JRC					GPS Rec. JLR-4331	KE50479 and after	